

G-6-VIOT
10/05/2000

Binder 2

Materials Technology II

1. Clinker Burning: Material Technological Aspects	3
2. Portland Cement Clinker	51
3. Refractory Materials and Coating Formation	105
4. Rings, Balls and Build-Ups	151
5. Fuels for Cement Kilns	173
6. Clinker Burning Behaviour of Heavy Metals	193
7. Kiln Dust	233
8. Quality Assurance	275
9. Quality Control: Concept, Control Plan, Procedures	305
10. Basic Principles of Sampling and Testing	339
11. Chemical and Physical Methods of the Laboratories	387
12. Automation in Quality Control	411
13. Statistics	435
14. Case Study	547

